

## Under Review Notification

**Raised By:** David Bain

**Product #:** D206-642

**Date:** 14.07.28

**Product Name:** 206 Skidtube

Part Number	Drawing/Document	"Y" or "N" Required								Instructions
		HOLD SHIPMENT	Red Tag/Quarantine Stock	Advise customers	Stop Production	Re-Work Stock	IPP Under Review	Blue File Under Review	ECN # Required	
D4366-1	Plate	Y	N	N	Y	N	N	N		TRYING TO IMPROVE FIT OF FWD WEARPLATE
D4366-041	Wearplate Assy	Y	N	N	Y	N	N	N		
D206-642-449	Run On Landing Wearplate Kit	Y	N	N	Y	N	N	N		
D206-642-451	Skidtube	Y	N	N	Y	N	N	N		

**Description of issue:**  
 FWD WEARPLATE ASSY WHEN INSTALLED IS SHOWING AN EXCESSIVE GAP BETWEEN THE PLATE AND THE SKIDTUBE. NEED TO ADJUST FWD MOUNTING HOLES TO IMPROVE FIT.

**Distribution:**

General Manager  
 Production Manager  
 Director Quality Assurance  
 Design Manager

Chief Engineer  
 Engineering Project Managers  
 Engineering Clerk  
 Marketing